KIMTECH[™]

Kimtech™A5 Sterile Hood

Donning Technique

- Select your hood; inspect package for vacuum seal; tear along notches toward the product to open.
- Pull out hood and unfold to locate face opening.
- Push one hand through opening while pulling down flaps with other hand.
- Position hood to pull over your head.
- Tilt head up, reach back and pull down flap in back.
- Pull front flap to a comfortable position; if hood has ties, pull back and tie.
- Complete donning with cleanroom mask and goggles.



Visit our website at www.kimtech.eu
Technical help: kimtech@kcc.com

