KIMTECH™

Kimtech™ M3 Sterile Pouch Face Mask

Post Hood Donning Technique

1 Carefully open the protective packaging.

2 While holding the mask through the protective packaging, reach in and separate the head band straps.

3 Pull bands over the head and secure while holding the protective packaging to avoid contaminating the mask.

4 Pinch nose wire into place.

5 Inhale and exhale to check for secure fit.

6 Put hood on over the mask.

Kimberly-Clark PROFESSIONAL™

Visit our website at **www.kimtech.eu**
Technical help: **kimtech@kcc.com**